Job Risk Analysis

				Jo	b Ris	sk Aı	nalys	sis										
Name(s) of Risk Team Members: J. Scott, S. Gill, Jack Barry		Point Valu Paramete			1				2	2 3		4				5		
Job Title: Vacuum System Work Job Number or Job Identifier: JRA 10-05			Frequence (B)	Frequency (B)			≤once/year			<pre><once month<="" pre=""></once></pre>	≤once/month ≤once/week		≤once/shift		>once/shift		ce/shift	
Job Description: Set up and Testing Residual Gas Analyzers			Severity (C)	Severity (C)			First Aid Only			Tedical Treatment Lost Time		Partial Disability			ity	Death or Perr Disabilit		
Training and Procedures List (optional): See Vacuum Group procedures Approved by: £. Lessard Date: 6-3-05 Rev. #:0				Likelihood (D)				nlikel	7	Unlikely	Possible	Probable			Multiple		ultiple	
Stressors (if applicabl None	e, please list all):		Reason for Revision Analyzed	(if ap	plicab	ole):Y	early	Upda	e, and	Different Job	Comments:							
					Bef	ore A	dditio	onal C	ontrols				Af	ter Ac	ldition	ıal Co	ontrols	
Job Step / Task	Hazard	Control(s)	Stressors Y/N	# of People A	Frequency B	Severity C	Likelihood D	Risk* AxBxCxD		dded to Reduce Risk	Stressors Y/N	# of People A	Frequency B	Severity C	Likelihood D	Risk* AxBxCxD	% Risk Reduction
Equipment Setup (Moving heavy equipment in shop)	Overexertion – injuries caused by excessive lifting, pushing, pulling, holding, or carrying of an object	Equipment on wheels, lift g back safety training, use of use of team lift, use of mech assist in lift	squat lift technique,	N	2	2	3	3	36	Work training is no course is for indivitools and equipment and who performs type operations we recommended for	individuals who have or injury from work-	N	2	2	3	2	24	25%
Equipment Setup (Slip on floor or wet surfaces in shop)	Falls on same level	Slip resistant footwear (e.g. housekeeping rules, work p		N	2	2	4	3	48	C-AD Housekeep Supervisory Pract Hazards were enh commitment to ho Supervisors were respective person addition, C-AD Se involvement in Ti- focused on Building	ing Policy and OPM 1.7, ice for Working with anced to reinforce C-AD busekeeping practices. reminded to have their nel read the OPM. In enior Management er I Inspections has	N	2	2	4	2	32	38%

Equipment Setup(Lifting or	Bodily reaction – injuries resulting from	Use of dollies to eliminate manual material handling tasks, use of portable lighting to	N	2	2	3	3	36								
pushing equipment into place and bolting together)	bending, climbing, loss of balance and slipping without falling	increase visibility at job site, ergonomic reviews of work, effective supervision at the job site, training, work planning														
Equipment Setup (Climbing on equipment)	Falls to lower level, such as falling from a ladder or over a railing	Fall protection for work above 4 feet, training, selecting the right ladder for the job, inspecting the ladder, climbing and descending the ladder properly, work planning, ESHG review of scaffolding when used	N	2	2	4	2	32								
Equipment Setup (Temporary lighting stands can fall over, equipment on wheels can roll into people)		Hardhats, safety glasses, wheel locks, work planning, chocking, barriers	N	2	2	3	2	24								
Equipment Setup (Removing heating tapes from boxes and applying them to beam line)	Fiberglass dust from heater tapes	Ventilation of the work area, gloves and tight fitting clothing to help prevent skin exposure problems by reducing direct contact with glass fibers, dust masks to help prevent or reduce the inhalation of small fiberglass particles, goggles that fit properly to prevent eye irritation.	N	2	2	2	4	24								
Equipment Setup (Contact with energized conductors in ion pumps, transformers, power distribution circuits)	Electrocution	Electrical safety training, written procedures for setting up transformers and heating elements; equipment meets UL or equivalent testing standards, PPE as required, Barriers, postings as required, NFPE 70 guidance	N	2	2	5	2	40	See Notes 1 through 4	N	2	2	4	2	32	20%
Turbo Vacuum Pump operation	Pressurized System (Vacuum)	Training, procedures, instrumentation, ventilated or open areas for exhaust, leak checks as you draw vacuum, PPE, venting paths if required	N	2	2	3	3	36								
Set up cleaning and leak check	Chemicals	PPE, CMS, training, procedures, limited amounts, labeling, proper containers.	N	2	2	2	3	24								
Bake Out (Contact with temporary task lighting, contact with heating elements)	Contact with temperature – extremes that result in such injuries as heat exhaustion, frost bite or burns	Heating blankets and foil cover the heating elements, posted signs that state "Bake Out In Progress", computer control and interlocks of system.	N	2	2	2	3	24								
Bake Out (Working in Radiation Area)	Ionizing radiation exposure	Work planning, use of time, distance and shielding to reduce exposure, ALARA review of high dose jobs, RWP, HP coverage as required.	N	2	2	1	2	8								
Equipment Setup and Bake Out	Being struck against an object - cuts and skin abrasions from working in tight spaces	Knee and elbow pads, steel-toe shoes, gloves, work clothing, ergonomic reviews of work.	N	2	2	3	3	36								
Returning set up to atmospheric pressure after testing	Pressurized system(vacuum)	Training, procedures, PPE, Venting gas(nitrogen), instrumentation.	N	2	2	3	3	36								

Moving and using pressurized cylinders	Dropping, missile	Training, proper moving carts, PPE, proper lifting rigs, SBMS guidance, proper regulators, proper storage	N	2	2	4	2	32				
Moving and using	Burns	Training, PPE, cryogenic safety review	N	2	2	3	3	36				
cryogenic dewar		committee, procedures, equipment maintenance										

Further Description of Controls Added to Reduce Risk:

- NOTE 1: OSHA Teams visited C-AD during the period October 20 through October 31, 2003 and recorded electrical non-compliances. All OSHA findings will be closed by 2006 by full compliance or with an equivalent level of safety. The status of the OSHA items are maintained in BNL's Compliance suite, and closed on a schedule commensurate with funding.
- NOTE 2: A compliance plan to have all electrical installations accepted by an Authority Having Jurisdiction (AHJ), as per 29CFR1910 Subpart S, has been implemented by BNL. UL, CSA, LLC or other NRTL accepted equipment will be acquired at BNL for all future installations. Prior installations shall be reviewed and accepted by qualified AHJs. The plan must be completed by 2009.
- NOTE 3: Full compliance with NFPA 70E was adopted by the C-AD in December 2005. NFPA 70E prescribes protective clothing to protect against shock and arc blast; thus reducing the severity and likelihood of an injury. It also prescribes training, which is currently fulfilled by taking the 2005 version of Electrical Safety 1 and by attending the C-AD 3-hour classroom course on electrical safety rules and PPE.
- NOTE 4: Contractor and vendor training in work planning and electrical safety has been improved. Plans to reach all contractors and vendors with regard to NFPA 70E requirements prior to performing work at BNL have been implemented. C-AD has obtained lists of all its vendors and suppliers and is ensuring that they take Electrical Safety 1 or have equivalent training if needed.

*Risk:	0 to 20	21 to 40	41-60	61 to 80	81 or greater
	Negligible	Acceptable	Moderate	Substantial	Intolerable